

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,920,387 B1
DATED : July 19, 2005
INVENTOR(S) : James W. Landes et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 16,

Line 6, after "delivery" insert -- command signals produced by said electronic controller; an engine speed sensor operatively connected with said electronic controller; --.

Line 19, delete "ration" and insert -- ratio --.

Line 51, after "engine" insert -- controller --.

Line 54, after "than" insert -- a --.


Line 54, after "time" insert -- and --.

Column 18,

Line 8, after "no" insert -- load --.

Signed and Sealed this

Seventh Day of February, 2006



JON W. DUDAS
Director of the United States Patent and Trademark Office